

BU-FM16-LM-CL-BH

Diagram 1 shows the first step of assembly. A long, thin metal rail with four pre-drilled holes is being attached to the top of a rectangular frame. A screwdriver is shown driving a screw into the first hole of the rail. A large black arrow indicates the direction of the screwdriver's movement. The number '1' is circled in the top right corner, indicating this is the first step.

